



MARINE HYDRAWRAP STRUCTURAL COMPOSITE REPAIR SYSTEM

Market

Marine

Challenge

A 3-inch main engine lube oil return line had become heavily deteriorated and oil saturated. A tee fitting in this lube oil return line began to leak.

Engineered Solution


A 4" Marine HydraWrap Tee Kit was chosen to provide a quick reliable solution to eliminate the leak.

Scope

The surface was prepared and all paint was stripped from the repair area. The shipyard general manager then applied primer. Finally, the Marine HydraWrap was applied.

Solution

Marine HydraWrap provided an ABS Design Approved repair for this lube oil system, which will prevent the need for future maintenance to keep this vessel operational.



HydraTech Engineered Products, LLC
HydraTech Field Services, LLC
10448 Chester Road, Cincinnati, Ohio 45215
Phone: (513) 827-9169 Fax: (513) 827-9171
<http://www.hydratechllc.com>

